

Manor Park Flood Damage Repair Works

Photo 1

Cutting holes in the rail iron in preparation for the wire rope.



Photo 2

Driving the rail iron near the top end of the Manor Park repair works.



Photo 3

Planting of willow wands at the downstream end of the works.



Stresscrete Flood Damage Repair Works

Photo 1

This photo shows the undermining of willows and the haul road above immediately downstream of the Chrystalls rock work.



Photo 2

This photo shows the area with the trees removed and the berm reconstructed.



Photo 3

The placement of rock rip rap on the edge of the reinstated berm.

